

propeller owner's manual & log book

D.O.A. -F.A.A. APPROVED MANUAL 115 K

"Compact" Models HC-C2Y, HC-C3Y, HC-F2Y, HC-F3Y, HC-F4Y, HC-E2Y, HC-E3Y, HC-G2Y, HC-G3Y, (P)HC-L3Y, BHC-L2Y, HC-H3Y, (P)HC-J3Y, BHC-J2Y, ()HC-I2Y, and ()HC-M2Y - Constant Speed and Feathering


January, 1979

MAINTENANCE RELEASE

Hub Serial No BG	516	-E2YL-2BSF / F7663-4
Blades Serial Nos:	#1_F82923	#2 F82925
	#3	* 4
The Propetter above was was found airworthy w	personal in some	
details of this repair are	personal in some	ce with the current F.A.A. Regulations and performed, for return to service. Pertinent under:

or,

Aircraft Specialists, Inc. Clark County Airport Sellersburg, In 47172



Work Performed:

Overhauled propel	ler &	complied	with	AD 7	7-12-
/// END ///					
Aircraft Specialists, Inc.	Clark Col	inty Airport	Sellersbu	rg, In	47172
(900) 35	6_2722	(812) 246	-6314		

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

ME	DESCRIP	DESCRIPTION OF WORK SIGNATU		SIGNATURE	RE	
-	MAI	NTENANCE RE	LEASE	78		
MAKE	Hartzell	_MODEL_HC-E2	YL-2BSF	HUB	-	
	L NO. BG516		•	134		
	ES SERIAL NOS. #1.	F82923	#2 F82925			
0 - 10 1	#3		#4			
The P	ropeller above was	OWEDMANNED in	accordance with	the current	-	
	Regulations and wa					
	of this repair are or			o. r or emione		
WOR	K ORDER # 2575	DATE 3-	20-87			
signed	10-11-1		STATION # 713-	-21		
0.9.00	1 / ~	FT SPECIALISTS	하다가 많다면 얼마나 하나 하는데 그 그리고 하다 하다 하다.			
		HITT LANE				
		LLE KY. 40222	(312) 246-63	14		

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

E	TACH	DESCRIPTION OF WORK	SIGNATURE
¥7	2297.96	Intelled peop on Rt. Eng. of N7230Y IAW Hartzell Installation Instructions	David & Strong Your TAGE
75	of Q	IAW Hartzell Installation Instructions	4+P47669392 (FOR A.D. COMPLIANCE
88		Disossembled dome assembly, check	ed lotcher,
		resealed and reassembled per H	artzell
		service manual 117D. WOH 799	1. This
		repair doesnot affect T50.	
		FAA Repair Station 503-70 Dane	DE PR 2349185
		FAA Repair Station 503-70 Jane "Quality Workmanship" TRI-COUNTY PROPELLERS, INC. ERIE. CO 80516 (303) 665-7905	(SENT IN AT ANNUAL - 2431.4)
		AD 77-12-06 Modified - No	YEARly limit - T.S.OH
	IN CREASON	1 to 12000 HRS under FR	AR PART 91 NEXT DUE 14291.90
2	,	AO 2002-09-08 PART B GU	I DURING OFH PART C
		AO 2002-09-08 PART B GU	RP -3

Serviced Propeller only as needed to repair leaking blade seals in accordance with Hartzell Manuals 117D Revision 14, 133C Revision 27, and 202A Revision 42. Complied with Hartzell Bulletin 226 Revision 1. Complied with Hartzell Service Letters 165, 189 Revision 2, 229 Revision 2, 267, and 293 Revision 1. Maxwell Aircraft Service, Inc. Minneapolis, MN 55429 CRS# UF2R211L Repair Order No. 117658 Carl E. Maxwell Aircraft Service (Service) (

Auth	ng National Aviation ority/Country:	AUTHORIZI	ED REL				117656	Track
MAXWEL	L AIRCRAFT SERVICESTAL AIRPORT ROAD	E, INC.					5. Wor Numb 117650	7.5.3
	Description:	8. Part Number:	9. Eligib	llity:*	10. Quantity:	11. Serial/Batch No	umber:	12. Status Works
6. Item:	 Description: HARTZELL PROPELLER 		N/A		1	BG-516		12. Status/Work: SERVICED
						-		
WORK PE	RFORMED ON THIS REPA	CE LETTERS 165, 189 REVISION 2, 229	O AN OVERHAUL.		ON 1.	rvice 🔲 Other reg	-1-4	
⊠ AĮ		bove were manufactured in conformi are in condition for safe operation. specified in Block 13.	ity to: 19.	Certifies th	at unless otherwise bed in Block 13 was gulations, part 43 s	e specified in block 13, the accomplished in accordand and in respect to that wor	e work id ance with	Title 14, Code of
15. Autho	rized Signature:	16. Approval/Author	orization No.: 20.	Authorized S	ignature:			pproval/Certificate No.: R211L
17. Name	(Typed or Printed):	18. Date:	100000	22. Name (Typed or Printed): CONRAD E. MAXWELL 2386511		23. Date (m/d/y): MAY 15, 2012		
			User/Installer	Resnonsil	hilities			
Where to in Block Block1.	he user/installer perform: 1, it is essential that the out nts in Blocks 14 and 19 do	the existence of this document alone s work in accordance with the national user/installer ensures that his/her airs o not constitute installation certification er/installer before the aircraft may be	does not automatica il regulations of an a worthiness accepts p on. In all cases, aire	lly constitute irworthiness a arts/compone	authority to install authority different on nts/assemblies from	than the airworthiness au the airworthiness author	thority of rity of the	country specified in
FAAF	orm 8130-3 (6-01)	*Installer must cross-ci	heck eligibility with	applicable to	echnical data.			NSN: 0052-00-012-9005
		r _{spi} ,						

6

Į

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

TACH TIME	DESCRIPTION OF WORK	SIGNATURE			
2899.57	N7230Y Piper PA30 S/N 30-254 05/30/2012 Right Tach 2899.57 Removed Right Propeller for repair. See Maxwell Aircraft Service, Inc. Work Order No. 117658. Installed Propeller on Right Engine. A&P 2661552 IA				
	•				
	•				