ANDERSON PROPELLER CO., INC.

Quality and Craftsmanship ... A Family Tradition for Over 45 Years



THE ANDERSON PROPELLER CO., INC.

320 Front St.E. • P.O.Box A • Brandon, MN 56315 Phone: (612) 524-2261

Propeller Logbook

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

NOTE DOWN

	LTACKTI	mc /		
DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE	
7-2-93	2534.0	9/H MCCAULEY-MODEL 10172	EM7653	9N 74573.
		CHECK PITCH AND TRACK.		
		GRIND, Dim. CHECK, CHROMIC		
		ANODIZED. PAINT EPOXY	Kenne	K& Smeus
And the same of th		GRAY AND BAZANCE.	cert #	2472281
The acco	aircraft and/or co	INTENANCE RELEASE MODEL/CITAL M 76-53 SERIAL NO. 7 4 5 7 3 mponent identified above was repaired and inspected in t FAA Regulations and was found Airworthy for return to of the repair are on file at this agency under		i
Worl	d Order No.		SON PROPELLER CO., 1	
Airw	orthiness Directives		treet East • P.O. Box	
and l	5/B 7-2-93	' '/ '/ '/ '/ '/ '/ '/ '/ '/ '/ '/ '/ '/		idon, MN 56315 lation No. NUPR439L
EA A	THE AN	DERSON PROPELLER CO., INC.	1.7	

FAA Approved Repair Station No. NUPR439L 320 Front Street East • P.O. Box A Brandon, Minnesota 56315

Class No. 1 & 2 Limited Phone: 612-524-2261

DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES, SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS

and the second second second second	and the second second second second second		
DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7-7-93	2534.0	Installed overhauled proper	Var
		on C-172B and torqued.	
		- END -	
esercione Mily in a second		Brad Olek AEP 4708838.	78
6-2496	2671	COMPLETEDHUNGALINGMOD	
			6,84695230E2IA
	Take A Again		
·			
A CONTRACTOR OF THE PROPERTY O	Harris Farmer and Control of the Con	The state of the s	The state of the s