

PROPELLER LOGBOOK

PROPELLER MODEL <u>HC-F3YR-IRF</u>

PROPELLER S/N DB-238B



PROPELLER MAINTENANCE RECORD

Position	
Propeller Model <u>HC-F3YR-IRF</u>	
Propeller S/N	
Blade Design <u>F8488A - 2R</u>	
Blade S/N's No. 1 K 21639 No. 2 K 21641	
No. 2 K21691 No. 3 K21692	
No. 4	
No. 5	I
No. 6	

Spinner Assembly Part No.

High/Feather	
Start Lock	
Low	
Reverse	
Aircraft Manufacturer	1
Aircraft Model	
S/N	
Registration	

PITCH RANGE

-

Description of all operations pertaining to Airworthiness Directives, Propeller A/C Date Service Documents, Overhaul, Major or Minor Repair, and Inspections. Hrs TSO TSN Changed low pitch to 11.2° Maxwell Aircraft Service Inc Mpls, MN, CRS#UF2R211L, Repair Order No. 110514 Coul 8. maprel 2386311 & GREAGED WITH AEROGHELL NO. 5

 Registration:
 N908EN
 Make:
 Cessna
 Model:
 206H
 S/N:
 20608105

 Date:
 3/12/2010
 Hobbs:
 729.8
 Tach:
 681.8

 Propeller:
 Hartzell HC-F3YR-1RF
 S/N:
 DB-238B
 TTSN:
 203.8

Performed propeller 100 hr/Annual Inspection IAW CFR 43.13 Appendix D, Cessna 200 Series Service Manual and Harrzell Service Instructions. Researched all FAA Airworthiness Directives through biweekly issue number 2010-05. All Airworthiness Directives in compliance at this time. Serviced propeller hub with Aeroshell #6 and dressed out any minor nicks IAW Hartzell Service Instructions.

I certify that this propeller has been inspected in accordance with the scope and detail of a 100 hr/Annual Inspection and is approved for return to service.

n Holmgren 476119246 IA

 Registration:
 NOSEN
 Make:
 Cessna
 Model:
 206H
 S/N:
 20608105

 Date:
 3/12/2010
 Hobbs:
 729.8
 Tach:
 681.8

 Propeller:
 Harzell HC-F3YR-1RF
 S/N:
 DB-238B
 TTSN:
 203.8

Performed propeller 100 hr/Annual Inspection IAW CFR 43.13 Appendix D, Cessna 200 Series Service Manual and Hartzell Service Instructions. Researched all FAA Airworthiness Directives through biweekly issue number 2010-05. All Airworthiness Directives in compliance at this time. Serviced propeller hub with Aeroshell #6 and dressed out any minor nicks IAW Hartzell Service Instructions

I certify that this propeller has been inspected in accordance with the scope and detail of a 100 hr/Annual Inspection and is approved for return to service.

on Holmgren 476119246 IA

Date	Prope TSN	eller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.	e deres a		
	ropo	llar	Entr				
R	0	on: N	908EN	Y Make: Cessna Model: 206H S/N: 20608105 Hobbs: 797.5 Tach: 746.8			
				F3YR-1RF S/N: DB-238B TTSN: 268.8			
				nnual Inspection IAW CFR 43.13 Appendix D, Cessna 200 Series Service Manual and Researched all FAA Airworthiness Directives through biweekly issue number 2011-			
06	06. All Airworthiness Directives in compliance at this time. Serviced propeller hub with Aeroshell #6 and dressed out any minor nicks IAW Hartzell Service Instructions.						
	I certify that this propeller has been inspected in accordance with the scope and detail of a 100 hr/Annual Inspection and is approved for return to service.						
-	a is approv		oturn to s		<u> </u>		
_				A	1.5		
				Aaron Holmgren 476119246 IA			
1	r i						
			- ¹				

Registration: N908EN Make: Cessna Model: 206H S/N: 20608105 Date: 3/31/2012 Hobbs: 849.2 **Tach:** 796.6 Propeller: Hartzell HC-F3YR-1RF S/N: DB-238B TTSN: 318.2

Performed propeller 100 hr/Annual Inspection IAW CFR 43.13 Appendix D, Cessna 206H annual inspection checklist and Hartzell Service Instructions. Researched all FAA Airworthiness Directives through biweekly issue number 2012-05. All Airworthiness Directives in compliance at this time. Serviced propeller hub with Aeroshell #6 and dressed out any minor nicks IAW Hartzell Service Instructions.

I certify that this propeller has been inspected in accordance with the scope and detail of a 100 hr/Annual Inspection and is approved for return to service.

Karon Holmgren

476119246 IA

 Registration:
 N908EN
 Make:
 Cessna
 Model:
 206H
 S/N:
 20608105

 Date:
 4/09/2013
 Hobbs:
 946.8
 Tach:
 892.3

 Propeller:
 Hartzell HC-F3YR-1RF
 S/N:
 DB-238B
 TTSN:
 414.3

Performed propeller 100 hr/Annual Inspection IAW CFR 43.13 Appendix D, Cessna 206H annual inspection checklist and Hartzell Service Instructions. Researched all FAA Airworthiness Directives through biweekly issue number 2013-07. All Airworthiness Directives in compliance at this time. Serviced propeller hub with Aeroshell #6 and dressed out any minor nicks IAW Hartzell Service Instructions.

I certify that this propeller has been inspected in accordance with the scope and detail of a 100 hr/Annual Inspection and is approved for return to service.

Aaron Holmgren

476119246 IA

 Registration:
 N908EN
 Make:
 Cessna
 Model:
 206H
 S/N:
 20608105

 Date:
 5/05/2014
 Hobbs:
 983.8
 Tach:
 928.3

 Propeller:
 Hartzell HC-F3YR-1RF
 S/N:
 DB-238B
 TTSN:
 450.3

Performed propeller 100 hr/Annual Inspection IAW CFR 43.13 Appendix D, Cessna 206H annual inspection checklist and Hartzell Service Instructions. Researched all FAA Airworthiness Directives through biweekly issue number 2014-09. All Airworthiness Directives in compliance at this time. Serviced propeller hub with Aeroshell #6 and dressed out any minor nicks IAW Hartzell Service Instructions.

I certify that this propeller has been inspected in accordance with the scope and detail of a 100 hr/Annual Inspection and is approved for return to service.

Aaron Holmgren 476119246 IA



 Annual
 Applied
 <thApplied</th>
 <thApplied</th>
 <thAp AACT N. A C. C. A SP. Critica Authorized Service Center Cassila Authorized Service Racilla

Date: 4-01-2016: Aircraft, N908EN, Type: 206H, S/N: 20608105: Hobbs: 1070.8: Tach: 1013-0, Total Time: 1013-0, Erop - Type: HC-F3YR-1RF, S/N, DB-238B, Time: 1013-0, SMOH: 1013-0, SMOH: 1013-0, Shop Crder #, 16-9412

Performed Annual (100 Hour Inspection of Propeller LA W. Cessina 206H - T206H series inspection checklist. Researched A D.s (hru or-weekly 2016-06.

Inspected spinner hub and biades. No blade nicks noted at this time

i certify that this Properer has been inspected in accordance with an Annual - 100 hour inspection and was determined to be in an aircorthy condition.

and Internet Signature

 Image: Second Second

Date: 4/19/2017, Aircraft: N908EN: Type: 206H; S/N: 20608105, Hobbs. 1116 1, Tach: 1056.2; Total Time: 1056 2: Prop - Type. HC-F3YR-1RF. S/N: DB-238B, Time. 1056.2, SMOH: 1056 2

Shop Order #: 17-9771

Performed Annual / 100 Hour Inspection of Propeller I.A.W. Cessna 206H / T206H series inspection checklist. Researched A.D.s thru bi-weekly 2017-07.

Inspected spinner, hub, and blades. Filed minor nicks out of blades. Greased propeller hub. I certify that this Propeller has been inspected in accordance with an Annual / 100 hour inspection and was determined to be in an airworthy condition.

Signature:

Page 4

Construction of the second A SS Airbort Approach Rd Duluth MN 55811
 AAO NACO ATR Girrus Authorized Service Center ves. Date T٤ Cessna Authorized Service Facility ections. Date: 5/04/2018; Aircraft: N908EN, Type: 206H; S/N: 20608105; Hobbs: 1155.7; Tach. 1093 5; Total Time: 1093 5: Prop - Type: HC-F3YR-1RF, S/N: DB-238B, Time: 1093 5, SMOH: 1093 5 Shop Order #: 18-10132 Performed Annual / 100 Hour Inspection of Propeller I.A W. Cessna 206H / T206H series inspection checklist. Researched A.D.s thru bi-weekly 2018-09. Inspected spinner, hub, and blades. Filed minor nicks out of blades. Greased propeller hub. I certify that this Propeller has been inspected in accordance with an Annual / 100 hour inspection and was determined to be in an airworthy condition. Signature ames Imberg A&P 2751176 A 2535 Airbort Approach Rd Duluth, MN 55811 C18) 727-2911 Cirrus Authorized Service Center Date: 4/17/2019; Aircraft: N908EN; Type: 206H; S/N: 20608105; Hobbs: 1183.0; Tach: 1119.3; Total Time: 1119.3; Prop - Type: HC-F3YR-1RF, S/N: DB-238B, Time: 1119.3, SMOH: 1119.3 Shop Order #: 19-10402 Performed Annual / 100 Hour Inspection of Propeller I.A.W. Cessna 206H / T206H series inspection checklist. Researched A.D.s thru bi-weekly 2019-06. Inspected spinner, hub, and blades. No biade nicks noted at this time. Greased propeller hub, I certify that this Propeller has been inspected in accordance with a 100 hour inspection and was determined to be in an airworthy condition Signature: James Imberg A&P



4535 Airport Approach Rd Duluth MN 55811

Date: 4/17/2020; Aircraft: N908EN; Type: 206H, S/N. 20608105; Hobbs: 1218.3; Tach: 1152.0; Total Time: 1152.0: Prop - Type. HC-F3YR-1RF, S/N: DB-238B, Time: 673.7, SMOH: 673.7 Shop Order #: 20-10762 Propeller was replaced June, 1, 2005 tach 478.0. Total time on prop is 673.7. Performed Annual / 100 Hour Inspection of Propeller I.A.W. Cessna 206H / T206H series inspection checklist. Researched A.D.s thru bi-weekly 2020-07. Inspected spinner, hub, and blades. Filed minor nicks out of blades. Greased propeller hub I certify that this Propeller has been inspected in accordance with a 100 hour inspection and was determined to be in an airworthy condition. nes Imly

Signature:

4535 Airport Approach Rd Duluth MN 55811 (218) 727-2911 MONACO ALR Cirrus Authorized Service Center

mberg A&P 2751176

Date: 4/13/2021; Aircraft: N908EN; Type: 206H; S/N: 20608105; Hobbs: 1235.1; Tach: 1167.2; Total Time: 1167.2; Prop - Type: HC-F3YR-1RF, S/N: DB-238B, Time: 688.9, SMOH: 688.9

Shop Order #: 21-11068

Performed Annual / 100 Hour Inspection of Propeller I.A.W. Cessna 206H / T206H series inspection checklist. Researched A.D.s thru bi-weekly 2021-07.

Inspected spinner, hub, and blades. No blade nicks noted at this time. Greased propeller hub. I certify that this Propeller has been inspected in accordance with a 100 Hour inspection and was determined to be in an airworthy condition.

Signature:

ames Imberg A&P 2751

Page 5

