

Piper PA28-235  
N 9450W

**TRW** HARTZELL PROPELLER  
OWNER'S MANUAL AND LOG BOOK

# PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model HC-C2YK-1BF

Blade Design \_\_\_\_\_

Diameter \_\_\_\_\_

Hub Ser. No. C416626

Blade Ser. Nos. \_\_\_\_\_

No. 1 F8468A-4 SER. F13547

No. 2 F8468A-4 SER. F13570

No. 3 N/A

PITCH RANGE

High \_\_\_\_\_ Low \_\_\_\_\_

Feather \_\_\_\_\_ Reverse \_\_\_\_\_

Governor Model \_\_\_\_\_

~~RIGHT ENGINE~~

~~Hub Model \_\_\_\_\_~~

~~Blade Design \_\_\_\_\_~~

~~Diameter \_\_\_\_\_~~

~~Hub Ser. No. \_\_\_\_\_~~

~~Blade Ser. Nos. \_\_\_\_\_~~

~~No. 1 \_\_\_\_\_~~

~~No. 2 \_\_\_\_\_~~

~~No. 3 \_\_\_\_\_~~

~~PITCH RANGE~~

~~High \_\_\_\_\_ Low \_\_\_\_\_~~

~~Feather \_\_\_\_\_ Reverse \_\_\_\_\_~~

~~Governor Model \_\_\_\_\_~~




DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
<del>Sept</del> 15, 1988		Annual inspection prop removed for overhaul & reinstalled after overhaul of same work done by Preebe Prop shop under WO 7495	
Oct 15 1988		FA 2061846 David M Gummy	
Nov 12 1989		Serviced Prop	Robert Pith IA 2089346
Dec 21 1990		Serviced Prop	Robert Pith IA 2089340
Jan 14 1992		Serviced Prop	Robert Pith IA 2089340
March 16 1993		Serviced Prop	Robert Pith IA 2089348
Oct 8 1994	2259:00	Prop overhauled Prop Shop	Robert Pith IA 2089340
Oct 2 1995		Serviced Prop	Robert Pith IA 2089340
Feb 13, 1997	2335:75	ANNUAL - Greased	Robert A. Norman AIP 298664021 IA
Feb 17, 1997	2451:57	ANNUAL - Greased	Robert A. Norman AIP 298664021 IA



**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
<p>Date <u>5-6-14</u> Total Time <u>2988.65</u>                      I Certify this <u>PROP</u> has been inspected                      in accordance with an annual <del>100</del> hour inspection                      and has been determined to be airworthy.</p>			
<p align="center">                       LEON C. LAMP      1852954AP/IA                 </p>			


Elite Aircraft service  
 Propeller Total Time: 3060.65 Hrs.

N9450W

August 1, 2015  
 Propeller Time SMOH: 810.65 Hrs.

\*I certify that this propeller has been inspected and serviced in reference to Piper Cherokee Service Manual, 100 Hour/Annual inspection and was determined to be in airworthy condition.

Mike Rowell A&P/IA 3038853



**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
8-7-2017	Tach 3074.2	CERTIFY THAT THIS <u>Propeller</u> <del>HAS BEEN</del> INSPECTED IAW AN ANNUAL INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION.	
		<u>Chuck Rantola</u> CHUCK RANTOLA A&P 47064532	