

PROPELLER LOGBOOK

PROPELLER MODEL HC-F3 YR-IRF

PROPELLER S/N _DB-185#

LOGBOOK #__

PROPELLER MAINTENANCE RECORD

Position	PITCH RANGE
Propeller Model HC-F3YR-IRF	High/Feather
Propeller S/N	Start Lock
Blade Design	Low
Blade S/N's No. 1	Reverse
No. 2	Aircraft Manufacturer
No. 3	Aircraft Model
No. 4	S/N
No. 5	Registration
No. 6	
Spinner Assembly Part No	

Date		eller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
2/20/01				Changed low pitch to 15.0° Maxwell Aircraft
				Service, Inc. Mpls. MN. CRS# UF2R211L
				Report Order No. 105522. Couls. muchel 2366511
, ,			d a consistent a	
7/18/01			56.2	Installed propeller on Cessna T206H, serial number
0				Taccosisy, in accordance with wipaire, Inc.,
				STC # SAOUSSCH. James Michael for
			B Transfer to the state of the	Wipaire Inc. CRS #
				RJWR390K
			di di di di Santa anno di di	
12/4/01	a secondary a	Brown and the second	1025	Removed propelle (Seasonal change)
Section 1			1	James Diehoff for
	0			Wigare, Inc. CRS# RJWR390K

5/1/02	116.5	Installed propeller (seasonal charge)
		Somet Nichoff for
		Domes Tichoff for Wipaire, Inc., CR\$ & RJWR390K
2.005 301.8	2715	
4,9 201.9	3/2,0	Dressed Blades in Conjuction with a 100hr Insp.
		I certify that this propeller has been Insp I Alw on
		Annual Insp. and was found to be in an airworthy Condition
We have the state of the state		REA 113686668 EA
		R29113686668 #A
B		
A STANDARD CONTRACTOR OF THE STANDARD CONTRACTOR		

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.		
	1. R	08184 M/N: I the follow Removed the reased the	N179ME 05-13-08 S/N: ving Maintenance: ne spinner and found the grease fitting leaking grease. Installed hub referencing the Hartzell Maintenance Manual 61-00-49. It gs for cleaning. Cleaned grease from the Spinner and Windshipory. Modern Aero, Inc. 14801 Pioneer Trail Eden Prairie, MN 55347 WO# 35964 FAA CRS # MZER198L	Removed the cowlings and hield. Leak check found to	

 Instrument was repaired and in regulations of the Federal Avia 	Work Order		
- Saite: 3 / 12 / 08 / Nill 1/1	Acit ilis. UT O. 6		
2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	G a	Name of the State Company of t	
The Authorities of the contraction of the contracti			
The state of the s			
A di transcribito de la processa de la compansión de la c	The second secon		
		and the state of t	
			The second section of the section of the second section of the section of the second section of the sect

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.						
Date: 4-	21-2020 Reg# : N179	ME Tach:	776 ACTT : 1256 PTT : 1186						
Inspec	ted prop and dres	sed blade	S.						
	y this prop has been to be in airworthy o		ted iaw an annual inspection and						
7	1		Seaplane Services						
Robei	t Timm, A&P269	9420IA	SURFSIDE SEAPLANE BASE LINO LAKES, MINNESOTA 651-792-4703						
Conjudentinoscopii Jai	Company of the State of State								
Special participation of the same of the s	B	West Population 1 1 1							
		A desirate and the second of t							
		1							
P A COMMUNICATION OF THE		A CONTRACT OF THE STREET							



PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION TOUGHE.

PROPELLER MODEL AND SERIAL B3D3 C432-B

HUB SERIAL 600191 BLADE SERIALS TK 293 , TK 299 , TK 317

D5519-2-13

Dag Book # 2

MAINTENANCE RECORD

DATE S	TOTAL		DESCRIPTION OF THE WORK PERFORMED		AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
3/30	0	0	Propeller hub S/N OOO 191, blade S/N TK 293, S/N TK 299 and S/N TK 317 has been installed on engine S/N L-10542-611 on aircraft—	Theic	Show
0/2/	TACH		T20608184	1	Mike Sharp
700	41	4	CESSNA T206H N179ME S/N T20608184 9-13-2000 INV# 1425 TACH: 41.4 HOBBS: 46.2 PROFILED PROPELLER BLADES. THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND HAS BEEN FOUND TO BE IN AIRWORTHY CONDITION.	Jun Coll	_ 280U (8AD)
		-	Thomas Galler 3800408TA		

MAINTENANCE RECORD

	The second second		1 manufacture and the property of the property	
DATE 2001	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
#9	HOURS	10ths		Q NUMBER
1/8/01	Tach: 56. Hobbs	ત્ર :- લ	Removed propeller this date. James liet wipaire, Inc.	CR\$ KJWR390K
12//	Tach	.5	Reinstalled propeller this date on Cessna James	
/14/01	Hobb		T20608184. for wipaire, hr.	R\$# RJWR390K
5/1	Toch	5	Removed propeller (Seasonal change) James Mich	of -Par
102	Hobbi	7	Wiparche CR	RJUR390K
		Total Control of the		The second of th
The second secon		d commentacy d		
The second second				